

EPT

EPT Template Revision

DATE: 4/26/04

YALE SECURITY GROUP


1902 Airport Road -

Monroe, NC 28110

TEL: 1-800-438-1951 FAX: 1-704-263-0789

Drawn By: Richard McKeown





EPTL Template Revision

DATE: 4/26/04

Drawn By: Richard McKeown


YALE SECURITY GROUP

1902 Airport Road -  
Monroe, NC  
TEL.: 1-800-434-1951 FAX: 1-704-  
283-0789

Figure 3: ROUTING DETAIL

THIS ROUTED CUTOUT IS TYPICALLY POSITIONED AS CLOSE AS POSSIBLE TO THE FACE OF THE DOOR ADJACENT TO THE HINGE.

- IF THE DOOR IS HOLLOW METAL, THE CUT SHOULD BE POSITIONED AS CLOSE AS POSSIBLE TO THE INSIDE SURFACE OF THE DOOR SHEET METAL WALL.
- IF THE DOOR IS WOOD (AS SHOWN HERE), LEAVE ABOUT 1/4" [6mm] BETWEEN THE EDGE OF THE CUT AND THE DOOR FACE FOR REASONABLE STRENGTH.



THESE ROUTED AREAS (TOP & BOTTOM) FOR THE RECESS OF THE SUPPORT COVER MOUNTING FLANGES ARE OPTIONAL AND ARE ONLY NECESSARY IF THERE IS NOT ADEQUATE SPACE BETWEEN THE EDGE OF THE DOOR AND THE FRAME WHEN THE DOOR IS CLOSED.

Routing Detail	DATE: 4/26/04			YALE SECURITY GROUP
Drawn By: Richard McKeown				1902 Airport Road - Monroe, NC TEL: 1-800-337-1551 FAX: 1-704-243-0779 